

Certificate of Conformity

Certificate No: 39626 **Date Inspected:** 23/01/2025
Date Of Issue: 23/01/2025 **Engineer:** Daisy
Next Inspection due: 23/01/2026

**Where applicable, Results are traceable to National Standards via UKAS Certified
Collimator System No. 2082**

Fleet No: PL/001 **Description:** Leica Piper 100 Pipe Laser
Serial No: P100-08295

| Test | Result |
|--|--------|
| Tested & Inspected To Manufacturers Specifications | Pass |

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....

JB Survey Ltd is an ISO9001:2015 registered company No. FS30408