

## Certificate of Conformity

**Certificate No:** 40153 **Date Inspected:** 11/03/2025  
**Date Of Issue:** 11/03/2025 **Engineer:** Daisy  
**Next Inspection due:** 11/03/2026

**Where applicable, Results are traceable to National Standards via UKAS Certified Collimator System No. 2082**

**Fleet No:** PL/034 **Description:** Leica Piper 100 Pipe Laser  
**Serial No:** P100-08812

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....*Daisy Loughran*.....