

## Certificate of Conformity

**Certificate No:** 39687

**Date Inspected:** 20/01/2025

**Date Of Issue:** 20/01/2025

**Engineer:** John

**Next Inspection due:** 20/01/2026

**Where applicable, Results are traceable to National Standards via UKAS Certified  
Collimator System No. 2082**

**Fleet No:** PL/055

**Description:** Leica Piper 100 Pipe Laser

**Serial No:** P100-12053

Test	Result
Tested & Inspected To Manufacturers Specifications	Pass

THE ABOVE EQUIPMENT HAS BEEN INSPECTED, ADJUSTED, WHERE NECESSARY, AND TESTED IN  
ACCORDANCE WITH JB SURVEY LTD QUALITY MANAGEMENT SYSTEM.

ALL ADJUSTMENTS ARE NOW WITHIN THE MANUFACTURER'S ORIGINAL SPECIFICATIONS.

Signed:.....

JB Survey Ltd is an ISO9001:2015 registered company No. FS30408